



[www.SILVER-FOX.net](http://www.SILVER-FOX.net)

## Fraction and Decimal Equivalents

1/64.....0.015625  
**1/32.....0.03125**  
3/64.....0.046875  
**1/16.....0.0625**  
5/64.....0.078125  
**3/32.....0.09375**  
7/64.....0.109375

**1/8.....0.125**

9/64.....0.140625  
**5/32.....0.15625**  
11/64...0.171875  
**3/16.....0.1875**  
13/64...0.203125  
**7/32.....0.21875**  
15/64...0.234375

**1/4.....0.25**

17/64...0.265625  
**9/32.....0.28125**  
19/64...0.296875  
**5/16.....0.3125**  
21/64...0.328125  
**11/32.....0.34375**  
23/64...0.359375

**3/8.....0.375**

25/64...0.390625  
**13/32.....0.40625**  
27/64...0.421875  
**7/16.....0.4375**  
29/64...0.453125  
**15/32.....0.46875**  
31/64...0.484375

**1/2.....0.5**

33/64...0.515625  
**17/32.....0.53125**  
35/64...0.546875  
**9/16.....0.5625**  
37/64...0.578125  
**19/32.....0.59375**  
39/64...0.609375

**5/8.....0.625**

41/64...0.640625  
**21/32.....0.65625**  
43/64...0.671875  
**11/16.....0.6875**  
45/64...0.703125  
**23/32.....0.71875**  
47/64...0.734375

**3/4.....0.75**

49/64...0.765625  
**25/32.....0.78125**  
51/64...0.796875  
**13/16.....0.8125**  
53/64...0.828125  
**27/32.....0.84375**  
55/64...0.859375

**7/8.....0.875**

57/64...0.890625  
**29/32.....0.90625**  
59/64...0.921875  
**15/16.....0.9375**  
61/64...0.953125  
**31/32.....0.96875**  
63/64...0.984375

**1.....1.0**